

APC Battery Power Chute Setup

Installing APC Battery backup to your Genmega Kiosk. **Kiosk must be plugged into internet to complete setup.**

1. Install UPS into Kiosk. Unplug the connection between the wall plug and power supply/power strip inside the kiosk. Plug in the UPS power and plug the power supply into the UPS (surge + battery) Plug in USB from UPS into Kiosk computer.
2. Boot Kiosk
3. From Main Kiosk Screen Press Esc. On keyboard
4. Insert USB-it will open a window
5. Run pcssetup program
6. Tap "yes" → "ok" → "next" → "I agree"
7. Make sure USB from UPS is plugged into the computer
8. Tap "yes" to auto search
9. Tap "next" on install location
10. Uncheck create user account
11. Tap "install" → Tap "next" → Tap "finish"
12. A browser will open, tap "advanced"
13. Tap "continue to localhost"
14. Tap "next"
15. Uncheck the two boxes tap "next"
16. Select "After the UPS has been on battery for"
17. Change to 60 seconds
18. Tap "Finish"
19. Close window
20. Press Windows Key on keyboard
21. Do proper Restart

When Power is removed from the UPS (outage, plug pulled) it will send a signal to the computer to properly shut down after 60 seconds. When power is restored to the UPS, the computer will start itself as normal.